

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,205,953

Examiner: Trinh Vo Dinh

Issued: April 17, 2007

Group: 2821

Inventor(s): Knadle, Jr., et al.

Docket No. 022.0008(1630)

For: DIRECTIONAL ANTENNA ARRAY

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Attn: Certificate of Corrections Branch
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for Patent Office mistakes under Rule 1.322 as follows:

Column 7, line 53, "clement" should be changed to --element--;
Column 7, line 65, "ray" should be changed to --array--;
Column 8, line 42, "army" should be changed to --array--;
Column 8, line 58, "element said" should be changed to -- element, said--;
Column 8, line 59, "balum" should be changed to --balun--;
Column 10, line 32, "fixst" should be changed to --first--.

These errors occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: May 15, 2007
Ingrassia Fisher & Lorenz, P.C.

/DANIEL R. POTE, REG. # 43011/
By: Daniel R. Pote
Attorney for Applicant(s)
Tel. (480) 385-5060